



Aerospace Testing Alliance

A Joint Venture of Jacobs, CSC, and GP

QUALITY ASSURANCE REQUIREMENTS

Welding rod/wire material must be marked by the manufacturer with ASME/AWS specifications, including certification, specification, manufacturer, trade name, lot number, size, length, and net weight.

Any material delivered unmarked will be rejected.

QUALITY NOTE 14