



Aerospace Testing Alliance

A Joint Venture of Jacobs, CSC, and GP

QUALITY ASSURANCE REQUIREMENTS

Subcontractor must provide certification of conformance on all precision measuring equipment used, certifying that the equipment is calibrated and maintains trace ability to the National Bureau of Standards.

One copy of certifications must be submitted to Commodity Specialist before beginning the contract.

QUALITY NOTE 21