



Aerospace Testing Alliance

A Joint Venture of Jacobs, CSC, and GP

QUALITY ASSURANCE REQUIREMENTS

Fiber-Optics cable. Vendor must provide one copy of certified test results stating specific values of attenuation (DB loss), transmission readings, etc.

Material received without the test results will be rejected.

QUALITY NOTE 23